



TOPOGRAPHICAL LEGEND :-

BANK BOTTOM	SOFT/SOFT SURFACE CHANGE
BANK TOP	KERB
BOUNDARY	KERB DROPP
BOUNDARY	ROAD EDGE
BUILDING	FENCE
OUT BUILDING	WALL
OH BUILDING CANOPY	STEPS
CANOPY (VEGETATION)	RAILWAYLINE
DITCH BOTTOM	OH ELECTRIC
DITCH TOP	OH TELECOMS
DRAINAGE CHANNEL	SURVEY EXTENTS
HARD/SOFT SURFACE CHANGE	X-SECTION
GATE	PYLON
CABLE STAY	TREE
BUSH	TOTAL PVT
BORSHOLE	BORSHOLE
SURVEY STATION	HACHURE

ABBREVIATIONS :-

AV	AIR VALVE	GA	GAS VALVE	SP	SECURITY FENCE (FENCE)
AW	AWAY DRAIN	GD	GULLY	SPC	SECURITY FENCE (POST)
BS	BLOCK STOP	MC	MANHOLE COVER	ST	STOP VALVE
BU	BURIED UTILITY	MF	MANHOLE	STP	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE
BUK	BURIED UTILITY	MS	MANHOLE	STW	STOP VALVE

NOTES :-

- Surveyed October 2015.
- Survey related to Ordnance Survey National Grid (OSTN02).
- Levels related to orthometric heights taken from GPS readings.
- Values on GPR strips show depth below ground.

CAUTION:

ADLEN ARE CERTIFIED UNDER BS ISO 9001:2008 FOR THE PROVISION OF UTILITY DETECTION & MAPPING SERVICES AND HAVE ENDED TO PROVIDE THE HIGHEST ACCURACY OF DATA POSSIBLE USING ADVANCED SYSTEMS. PROCEDURES AND THE APPLICATION OF THE MOST RELIABLE DETECTION & LOCATION TECHNOLOGY AVAILABLE. ALL MEASUREMENTS ARE TAKEN FROM THE SURFACE AND WHERE BEST PRACTICE IS IMPLEMENTED, ERRORS MAY OCCUR IN RELATION TO THE POSITIONS AND DEPTHS GIVEN FOR BURIED PLANT, CHAMBERS, PIPES & CABLES. IN CERTAIN CASES THIS ERROR MAY BE IN EXCESS OF 30% OF THE VALUE STATED. THERE MAY BE SERVICES PRESENT THAT ARE NOT DETECTED BY THE CURRENT TECHNOLOGY OR SITE RELATED FACTORS NOT FORECAST AT THE TIME OF THE SURVEY. COULD NOT BE LOCATED, THEREFORE DO NOT APPEAR ON THIS DRAWING; THIS ARE ADVISED TO EXERCISE CAUTION OF RIGHT AND BEST PRACTICE WHEN EXCAVATING ON THIS SITE. LIABILITY FOR ERRORS, OMISSIONS OR EXCEPTIONS WILL BE ACCEPTED BY ADLEN.

- Service located by Electro Magnetic Detection e.g. Metallic pipes & cables
- Service located by Electro Magnetic Detection e.g. Metallic pipes & cables
- Service located by Ground Penetrating Radar e.g. Plastic pipes or services which could not be detected using other methods

ORIGINAL SIZE: A0 - DO NOT SCALE!

DATE	REVISIONS	Signed
------	-----------	--------

CLIENT : ADLEN
 PROJECT NAME : UNIT 5, DELTA COURT, SKY BUSINESS PARK, ROBIN HOOD AIRPORT, DN9 3GN
 PROJECT TITLE : MODELLING OF BADGER SETTS AND TOPOGRAPHICAL SURVEY

SURVEYOR : *** DRAWN : *** APPROVED : ***
 DIGITAL FILE : ORIGINAL SIZE: A0 SCALE: NTS SHEET 1 of 1

DRAWING No: REV:



DELTA COURT, SKY BUSINESS PARK, ROBIN HOOD AIRPORT, DONCASTER, DN9 3GN
 tel: 01302 802200, fax: 01302 802213, email: info@adien.com - web: www.adien.com
 1ST Floor, Vassart Place, Unit 2/8 Inchmure Road, Whitehall Ind Est, Bathgate, EH48 2EP
 tel: 0800 612 9169, email: Royth@adien.com - web: www.adien.com

Adien Limited 2015